

REPORT OF THE MARITIME SAFETY COMMITTEE
ON ITS SEVENTY-EIGHTH SESSION
Corrigendum



IMO

E

MARITIME SAFETY COMMITTEE
78th session
Agenda item 26

MSC 78/26/Add.2/Corr.1
29 July 2004
ENGLISH ONLY

**REPORT OF THE MARITIME SAFETY COMMITTEE
ON ITS SEVENTY-EIGHTH SESSION**

Corrigendum

Annex 20 to MSC 78/26/Add.2 on Adoption of the IMO unique company and registered owner identification number scheme (resolution MSC.160(78))

Paragraph 6 of the annex to annex 20 is replaced by the following:

“6 The IMO unique company and registered owner identification number should be inserted on the following documents:

- .1 Document of Compliance; Safety Management Certificate, Interim Document of Compliance; and, Interim Safety Management Certificate, required by the International Safety Management (ISM) Code;
- .2 Continuous Synopsis Record required by SOLAS regulation XI-1/5; and
- .3 International Ship Security Certificate and Interim International Ship Security Certificate, required by the International Ship and Port Facility Security (ISPS) Code.”

REPORT OF THE MARITIME SAFETY COMMITTEE
ON ITS SEVENTY-EIGHTH SESSION
Corrigendum