

ANNEX
Acts of piracy and armed robbery allegedly committed against ships reported by
Member States or international organizations in consultative status

N°	Ship Name Type of Ship Flag Gross Tonnage IMO Number	Date Time	Position of the incident*	Details of the incident	Consequences for crew, ship, cargo	Action taken by the master and the crew	Was the incident reported to the coastal authority? Which one?	Reporting State or international organization	Coastal State Action Taken
1	2	3	4	5	6	7	8	9	10
IN TERRITORIAL WATERS									
1	Danum 53 / Linau 135 Tug Malaysia 269 9414864	06/04/2024 16:45 LT	MALACCA STRAIT South of Tanjung Ramunia, Johor, (Malaysia), in the westbound lane of the TSS Malaysia 01° 18.59' N 104° 15.77' E	While the tug boat towing barge was underway, the master noticed a sampan alongside the barge. Three perpetrators were seen leaving the barge with some copper coils and fibre boards. The crew was mustered and accounted for. The crew was not injured. The tug boat and barge last port of call was Bintulu, Sarawak, East Malaysia and was bound for Singapore Pilot Eastern Boarding Ground "A". The master reported to Singapore Vessel Traffic Information System (VTIS) East. Safety navigational broadcast was initiated. The Republic of Singapore Navy's (RSN) Maritime Security Task Force (MSTF) and Singapore Police Coast Guard were notified. Information was shared with the Malaysian authorities.	The crew was not injured. Some copper coils and fibre boards were stolen.	The crew was mustered and accounted for.	Yes Incident was reported to Singapore VTIS East.	ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)	Safety navigational broadcast was initiated. The RSN's MSTF and Singapore Police Coast Guard were notified. Information was shared with the Malaysian authorities.
2	Casanova Bulk carrier Bahamas 92249 9454151	14/04/2024 02:47 LT	MALACCA STRAIT Singapore Straits Indonesia 01° 04.50' N 103° 40.90' E	Five robbers armed with pistols boarded a ship underway. They pointed pistols at the duty engineer, tied his hands and placed him face-down on the floor. General alarm raised, PA announcement made and crew mustered. VTIS informed. The robbers escaped with the stolen items. A search was made and ship's engine spares were identified as stolen.	Duty engineer taken hostage and ship's engine spares stolen	General alarm raised, PA announcement made and crew mustered	Yes Singapore VTIS	ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP) PRC relayed the message to Singapore Police Coast Guard. (IMBKL)	Singapore VTIS maintained regular contact via VHF.
3	Bongawan 9 / Hexagro 9 Tug Malaysia 141 9515371	14/04/2024 10:20 LT	MALACCA STRAIT Approx. 4.3 nm east of Tanjung Penyusop, (Malaysia), in the westbound lane of the TSS Malaysia 01° 20.93' N 104° 21.07' E	While underway, the master reported to Singapore VTIS East via VHF Channel 10, that he sighted three to four perpetrators alongside the unmanned barge in three sampans. The master raised the alarm and mustered the crew. At 1040 hrs, the master reported that the perpetrators left the barge. The master further reported that some scrap metals were stolen from the barge. All crew members were accounted for with no injuries, and no assistance required. Safety navigational broadcast was initiated. The RSN's MSTF and Singapore Police Coast Guard were informed. Information was shared with the Malaysian authority.	The crew was not injured. Some scrap metals were reported stolen.	The master raised the alarm and mustered the crew. The master reported the incident to Singapore VTIS East.	Yes The master reported the incident to Singapore VTIS East.	ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)	Safety navigational broadcast was initiated. The RSN's MSTF and Singapore Police Coast Guard were notified. Information was shared with the Malaysian authority.
IN PORT AREA									

* The position given should be as accurate as possible including latitude and longitude co-ordinates or as a bearing and distance from a conspicuous landmark
NOTE: SOUTH AMERICA: (A) - Atlantic; (C) - Caribbean; (P) - Pacific

1	Shakespeare Bay Bulk carrier Hong Kong, China 19801 9542661	03/04/2024 18:10 UTC	MALACCA STRAIT Kuala Tanjung Port, Indonesia Indonesia 03° 22.29' N 099° 28.20' E	Three robbers armed with knives boarded a berthed ship. They entered the engine room, took hostage the duty crew and tied his hands. The robbers released the duty crew before escaping with stolen ship's engine spare parts.	Duty crew was taken hostage and ship's engine spare parts stolen.	Reported to agent	Yes Local agent	PRC relayed the message to Indonesian Marine Police HQ. (IMBKL) ReCAAP ISC via ReCAAP Contact Point (Hong Kong) (ReCAAP)	NA
2	Maersk Chattogram Container ship Singapore 31649 9761023	08/04/2024 00:45 LT	INDIAN OCEAN Chattogram Outer Anchorage, Bangladesh Bangladesh 21° 09.00' N 091° 07.00' E	While anchored, the duty watchman noticed two perpetrators onboard the deck, and managed to escape onboard a country boat. Upon inspection, it was found out that 600 ltrs of paint, 150 mtrs of safety chain, 16 pcs of brass fire hydrant caps, and 2 pcs of fire houses were stolen. The incident was immediately reported to the Bangladesh Coast Guard and Port Control Authority. The crew was not injured. Bangladesh Coast Guard carried out patrol in the incident area, and recovered all stolen ships items and handed over to the ship master. It is recommended and advised for all ships, low draft ships, and tug boats heading towards Bangladesh ports and territorial waters, to maintain communication with law enforcement agencies (LEAs) through HF/ VHF channels 12 and 16 for help.	The crew was not injured. 600 ltrs of paint, 150 mtrs of safety chain, 16 pcs of brass fire hydrant caps, and 2 pcs of fire houses were stolen, and was later recovered by the authorities.	The master immediately reported the incident to the Bangladesh Coast Guard and Port Control Authority. The crew conducted inspection onboard.	Yes Incident was reported to Bangladesh Coast Guard and Port Control Authority.	ReCAAP ISC via ReCAAP Focal Point (Bangladesh) (ReCAAP) PRC relayed the message to Bangladesh Coast Guard. (IMBKL)	As per directive, Bangladesh Coast Guard carried out patrol in the incident area, and recovered all stolen ships items and handed over to the Ships master. Bangladesh Focal Point recommended and advised all ships, low draft ships, and tug boats heading towards Bangladesh ports and territorial waters, to maintain communication with LEAs through HF/ VHF channels 12 and 16 for help.
3	Asian Trader Container ship Cyprus 9966 9245689	12/04/2024 23:48 UTC	SOUTH AMERICA (A) Georgetown Port, Guyana Guyana 06° 48.59' N 058° 10.10' W	A ship was boarded by three unauthorised persons armed with knives during berthing manoeuvres. Alarm raised and crew mustered, resulting in the persons escaping. Incident reported to VTS. A patrol boat searched the seaward side of the vessel while a security team performed a search on the vessel.	Nil	Alarmed Raised, Crew mustered and a search was carried out.	Yes Port Authorities and Local agent	PRC relayed the message to Guyana Coast Guard. (IMBKL)	A patrol boat searched the seaward side of the vessel while a security team performed a search on the vessel.
4	Solar Roma Product tanker Lao People's Democratic Republic 18335 9887372	13/04/2024 18:47 UTC	MALACCA STRAIT Balikpapan Anchorage, Indonesia Indonesia 01° 17.96' S 116° 47.93' E	The tanker at anchor was boarded by four perpetrators through the anchor chain. They broke into the fore-castle store and escaped with ship's stores and properties. Incident reported to Balikpapan port control.	Ship's stores and properties stolen	Crew mustered and a search was carried out.	Yes Balikpapan Port Control	PRC relayed the message to Indonesian Marine Police HQ. (IMBKL)	NA

MSC.4/Circ.336
ANNEX