

**ANNEX I**  
**Acts of piracy and armed robbery allegedly committed against ships reported by**  
**Member States or international organizations in consultative status**

N°	Ship Name Type of Ship Flag Gross Tonnage IMO Number	Date Time	Position of the incident*	Details of the incident	Consequences for crew, ship, cargo	Action taken by the master and the crew	Was the incident reported to the coastal authority? Which one?	Reporting State or international organization	Coastal State Action Taken
1	2	3	4	5	6	7	8	9	10
<b>IN TERRITORIAL WATERS</b>									
1	Jal Kamal Bulk carrier Marshall Islands 35835 9875056	06/08/2023 16:50 UTC	MALACCA STRAIT Approximately 6.2 nm from Tanjung Tondong (Indonesia), in the eastbound lane of the TSS Indonesia 01° 16.72' N 104° 16.67' E	While underway, the master reported to Singapore Vessel Traffic Information System (VTIS) East that one perpetrator was sighted in the engine room. The master raised the ship's emergency alarm and all crew mustered. Upon hearing the alarm, the perpetrator escaped immediately. Items including main engine spares, generator spares and fuel injection pump were stolen. The crew was not injured.  Safety navigational broadcast was initiated. The Republic of Singapore Navy's (RSN) Maritime Security Task Force (MSTF) and Singapore Police Coast Guard were notified of the incident. Information of the incident was shared with the Indonesian and Malaysian authorities.	The crew was not injured.  Items stolen include main engine spares, generator spares and fuel injection pump.	The master raised the ship's emergency alarm and all crew mustered.	Yes The master reported the incident to Singapore VTIS East.	ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)  PRC relayed the message to Singapore Police Coast Guard (IMBKL)	Safety navigational broadcast was initiated. The RSN's MSTF and Singapore Police Coast Guard were notified of the incident. Information of the incident was shared with the Indonesian and Malaysian authorities.
2	Osaka Star Bulk carrier Liberia 47003 9740809	08/08/2023 13:50 UTC	MALACCA STRAIT Approximately 4.1 nm from Pulau Cula (Indonesia), in the Straits of Malacca & Singapore Indonesia 01° 02.84' N 103° 38.61' E	While underway, the master reported to Singapore Vessel Traffic Information System (VTIS) West that four perpetrators were sighted in the engine room. The ship's alarm was raised and crew mustered. A search was conducted on board the ship and at about 2245 hrs, the search was completed with no further sighting of the perpetrators. All crew members were safe and some main engine spare parts were missing. The ship continued to proceed to Singapore to pick up pilot at Pilot Eastern Boarding Ground "B" at 0100 hrs.  Safety navigational broadcast was initiated. The Republic of Singapore Navy's (RSN) Maritime Security Task Force (MSTF) and Singapore Police Coast Guard were notified of the incident. Information of the incident was shared with the Indonesian and Malaysian authorities.  Singapore Police Coast Guard boarded and searched the ship when she was anchored in Singapore port, and confirmed no perpetrators were found on board.	All crew members were safe.  Some main engine spare parts were stolen.	The ship's alarm was raised and crew mustered.  A search was conducted on board the ship.	Yes The master reported to Singapore VTIS West.	ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)  PRC relayed the message to Singapore Police Coast Guard and Indonesian Marine Police HQ. (IMBKL)	Safety navigational broadcast was initiated. The RSN's MSTF and Singapore Police Coast Guard were notified of the incident. Information of the incident was shared with the Indonesian and Malaysian authorities.  Singapore Police Coast Guard boarded and searched the ship when she was anchored in Singapore port, and confirmed no perpetrators were found on board.

\* The position given should be as accurate as possible including latitude and longitude co-ordinates or as a bearing and distance from a conspicuous landmark  
NOTE: SOUTH AMERICA: (A) - Atlantic; (C) - Caribbean; (P) - Pacific

3	Doric Warrior Bulk carrier Liberia 51208 9453511	08/08/2023 14:35 UTC	MALACCA STRAIT Approximately 3.5 nm from Pulau Cula (Indonesia), in the eastbound lane of the TSS Indonesia 01° 02.63' N 103° 39.22' E	Ten robbers armed with knives and steel bars boarded a bulk carrier underway and entered the Engine Room. They took hostage and tied up the 3/E in the Engine Control Room. Prior to escaping, the robbers stole engine spares. On activation of the dead man alarm, the C/E found the 3/E tied up and immediately informed the Master. General alarm raised and incident reported to Singapore VTS. Coast Guard boarded the vessel for investigation.	Robbers took hostage and tied up 3/E and escaped with stolen ship's engine spares.	Alarm raised	Yes Singapore VTS	ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)  PRC relayed the message to Singapore Police Coast Guard and Indonesian Marine Police HQ (IMBKL)	Safety navigational broadcast was initiated. The RSN's MSTF and Singapore Police Coast Guard were notified of the incident. Information of the incident was shared with the Indonesian and Malaysian authorities.  Singapore Police Coast Guard boarded and searched the ship when she was anchored in Singapore port, and confirmed no perpetrators were found on board.
4	Sophocles Graecia Bulk carrier Cyprus 44095 9843730	08/08/2023 19:30 UTC	MALACCA STRAIT Approximately 6.2 nm from Tanjung Tondong (Indonesia), in the eastbound lane of the TSS Indonesia 01° 04.44' N 103° 42.20' E	While underway, the master reported to Singapore VTIS West that three perpetrators were sighted in the engine room. The ship's alarm was raised and crew mustered. A search was conducted on board the ship and at about 0447 hrs, the search was completed with no further sighting of the perpetrators. All crew members were safe. At about 0521 hrs, the master updated that some main engine spare parts were missing. The ship continued to proceed to Singapore to pick up pilot at Pilot Eastern Boarding Ground "B" at 0530 hrs.  Safety navigational broadcast was initiated. The RSN's MSTF and Singapore Police Coast Guard were notified of the incident. Information of the incident was shared with the Indonesian and Malaysian authorities.  Singapore Police Coast Guard boarded and searched the ship when she was anchored in Singapore port, and confirmed no perpetrators were found on board.	All crew members were safe.  Some main engine spare parts were stolen.	The ship's alarm was raised and crew mustered.  A search was conducted on board the ship.	Yes The master reported to Singapore VTIS West.	ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)  PRC relayed the message to Singapore Police Coast Guard and Indonesian Marine Police HQ (IMBKL)	Safety navigational broadcast was initiated. The RSN's MSTF and Singapore Police Coast Guard were notified of the incident. Information of the incident was shared with the Indonesian and Malaysian authorities.  Singapore Police Coast Guard boarded and searched the ship when she was anchored in Singapore port, and confirmed no perpetrators were found on board.
<b>IN PORT AREA</b>									
1	CNC Pluto Container ship Malta 18826 9760586	10/08/2023 16:02 UTC	SOUTH CHINA SEA Manila Anchorage, Philippines Philippines 14° 35.58' N 120° 50.52' E	Eight robbers armed with guns boarded an anchored ship. They took the duty crew hostage, tied him up and stole his cell phone. Alarm raised and the crew mustered. Seeing the alerted crew, the robbers escaped. The incident was reported to VTMS and Philippines Coast Guard boarded the ship for investigation.	Robbers took the duty crew hostage, tied him up and stole his cell phone.	Alarm raised, ship's whistle sounded, and crew mustered	Yes VTMS Manila, Philippines	PRC relayed the message to Philippines Coast Guard HQ. (IMBKL)	Coast guard boarded the ship for investigation.
2	Shotan Chemical tanker Panama 5518 9709271	23/08/2023 18:50 UTC	MALACCA STRAIT Dumai Inner Anchorage, Indonesia Indonesia 01° 43.18' N 101° 26.22' E	Duty crew onboard an anchored tanker noticed three robbers armed with knives near the engine room. The robbers threatened the duty crew, who fled from the vicinity and raised the alarm resulting in the robbers escaping with stolen engine spare parts.	Stolen engine spare parts	Alarm was raised.	Yes NA	PRC relayed the message to Indonesian Marine Police HQ (IMBKL)	NA

3	SLNC Severn Bulk carrier United States 33737 9629988	29/08/2023 09:00 UTC	MALACCA STRAIT Berth 112, Belawan Port, Indonesia	Duty crew onboard a berthed ship noticed three robbers armed with knives at the forecastle. Alarm raised and crew mustered. Upon hearing the alarm, the robbers escaped with stolen ship's stores. Incident reported to the local authorities through the local agent.	Ship's stores were stolen.	Alarm raised and crew mustered	Yes Local Authorities	PRC relayed the message to Indonesian Marine Police HQ. (IMBKL)	Indonesian Marine Police HQ boarded the ship for investigation.
									MSC.4/Circ.328 ANNEX I

\* \* \*

**ANNEX II**  
**Acts of piracy and armed robbery allegedly attempted against ships reported by**  
**Member States or international organizations in consultative status**

N°	Ship Name Type of Ship Flag Gross Tonnage IMO Number	Date Time	Position of the incident*	Details of the incident	Consequences for crew, ship, cargo	Action taken by the master and the crew	Was the incident reported to the coastal authority? Which one?	Reporting State or international organization	Coastal State Action Taken
1	2	3	4	5	6	7	8	9	10
<b>IN PORT AREA</b>									
1	Anggun Rescue/standby ship Malaysia 2339 9390056	05/08/2023 23:52 UTC	WEST AFRICA Takoradi Anchorage, Ghana 04° 50.00' N 001° 43.00' W	Around five unauthorised persons in a canoe approached and attempted to board an anchored vessel twice within 48 hours. Alert crew raised the alarm resulting in the persons aborting the attempted boarding and moving away. Incident reported to local authorities via VHF.	Nil	Alarm raised and crew mustered	Yes Local Authorities	PRC relayed the message to Ghana Authorities (IMBKL)	NA

MSC.4/Circ.328  
ANNEX II

\* The position given should be as accurate as possible including latitude and longitude co-ordinates or as a bearing and distance from a conspicuous landmark  
NOTE: SOUTH AMERICA: (A) - Atlantic; (C) - Caribbean; (P) - Pacific