

ANNEX Acts of piracy and armed robbery allegedly committed against ships reported by Member States or international organizations in consultative status									
N°	Ship Name Type of Ship Flag Gross Tonnage IMO Number	Date Time	Position of the incident*	Details of the incident	Consequences for crew, ship, cargo	Action taken by the master and the crew	Was the incident reported to the coastal authority? Which one?	Reporting State or international organization	Coastal State Action Taken
1	2	3	4	5	6	7	8	9	10
IN INTERNATIONAL WATERS									
1	Name Withheld General cargo ship Saint Kitts and Nevis 5014	26/04/2026	INDIAN OCEAN Around 20nm NNE of Garacad, Somalia Somalia 07° 13.00' N 049° 32.00' E	While underway, the cargo ship was boarded and hijacked by armed persons. The incident is ongoing and being monitored by Authorities.	Persons took hostage all crew members and hijacked the ship	NA	Yes MSCIO & UKMTO	IMBKL	Authorities are monitoring the ship
IN TERRITORIAL WATERS									
1	Lowlands Island Bulk carrier Panama 36140 9984534	09/04/2026 03:40 LT	MALACCA STRAIT Approximately 3 nm off Pulau Cula (Indonesia), in the eastbound lane of the TSS Indonesia 01° 03.00' N 103° 39.70' E	While underway, four perpetrators were sighted in the engine room. One of the perpetrators carried a knife, and another perpetrator carried a gun-like object and a knife. The ship's general alarm was activated and crew mustered. After conducting a search onboard, the master confirmed there was no further sighting of the perpetrators and some engine spares were stolen. All crew members were accounted for, with no injuries reported. The incident was reported to Singapore Vessel Traffic Information System (VTIS). Safety broadcast on anti-piracy watch was carried out to warn all vessels to maintain a vigilant watch at all times in the Singapore Strait (SS). The Republic of Singapore Navy (RSN) and Singapore Police Coast Guard (SPCG) were notified of the incident. Information was shared with the Indonesian authority. The SPCG boarded the ship for security checks at Singapore anchorage, with no perpetrators found onboard.	Some engine spares were stolen. The crew were not injured.	The ship's general alarm was activated and crew mustered to conduct a search onboard.	Yes The incident was reported to Singapore VTIS.	ReCAAP-ISC	Safety broadcast on anti-piracy watch was initiated to warn all vessels to maintain a vigilant watch at all times in the SS. The RSN and SPCG were notified of the incident. Information was shared with the Indonesian authority. The SPCG boarded the ship for security checks at Singapore anchorage, with no perpetrators found onboard.
2	HK Tug 8/LKH 2882 Tug Singapore 299 9557537	13/04/2026 21:44 LT	MALACCA STRAIT Approx 3 nm from Pulau Nongsa, Indonesia, in the eastbound lane of the TSS Indonesia 01° 15.32' N	While underway, the Master observed a sampan alongside the barge, with approximately two perpetrators on board. The perpetrators subsequently escaped from the barge via the sampan. The perpetrators were not armed. The crew were not injured. Some scraped metals were stolen. The incident was reported to Singapore MPA (flag State).	Some scraped metals were stolen. The crew were not injured.	Not stated.	No	ReCAAP-ISC	Not stated
3	MV Baleno 8 Passenger ship Philippines	17/04/2026 16:40 LT	SOUTH CHINA SEA Waters off Barangay Cuta, Batangas City Philippines 13° 44.38' N 121° 02.93' E	While grounded, five perpetrators carried knives boarded the vessel. The perpetrators threatened the crew while escaping. Some metal parts and generator wirings were stolen. One crew member promptly reported the incident to Coast Guard Sub-Station (CGSS) Batangas City when the perpetrators had already fled the vicinity. Upon receiving the report, CGSS Batangas City deployed personnel to render necessary assistance. All five perpetrators were arrested and sent to the station for investigation.	Some metal parts and generator wirings were stolen. The crew were threatened.	A crew promptly reported the incident to CGGS Batangas City.	Yes CGGS Batangas City	ReCAAP-ISC	Upon receiving the report, CGSS Batangas City deployed personnel to render necessary assistance. All five perpetrators were arrested and sent to the station for investigation.

* The position given should be as accurate as possible including latitude and longitude co-ordinates or as a bearing and distance from a conspicuous landmark
NOTE: SOUTH AMERICA: (A) - Atlantic; (C) - Caribbean; (P) - Pacific

4	MTT Tahan/MTT Tioman Tug Malaysia 192 1149815	19/04/2026 02:00 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 08.22' N 103° 28.26' E	Two unauthorised persons boarded a barge under tow. Nearby vessels alerted the tug master who boarded the barge for inspection resulting in the persons escaping. It was reported that two containers onboard the barge were broken into and contents stolen. Incident reported to the local authorities.	Two containers onboard the barge were broken into and contents stolen	Incident reported to the local authorities	Yes Local authorities	IMBKL	NA
5	Aliado Bulk carrier Liberia 89651 9300570	20/04/2026 03:58 LT	MALACCA STRAIT Approximately 6.3 nm off Pulau Cula, Indonesia, in the eastbound lane of the TSS Indonesia 01° 04.19' N 103° 36.66' E	While underway, one perpetrator was sighted in the engine room. The ship's general alarm was activated. All crew mustered and accounted for. A search was conducted with no further sighting of the perpetrators. The crew were not injured and nothing was stolen. The incident was reported to Singapore Vessel Traffic Information System (VTIS). Safety broadcast on anti-piracy watch was carried out to warn all vessels to maintain a vigilant watch at all times in the Singapore Strait (SS). The Republic of Singapore Navy (RSN) and Singapore Police Coast Guard (SPCG) were notified of the incident. Information was shared with the Indonesian authority.	Nothing was stolen. The crew were not injured.	The ship's general alarm was activated. All crew mustered and accounted for. A search was conducted with no further sighting of the perpetrators.	Yes The incident was reported to Singapore VTIS.	ReCAAP-ISC	Safety broadcast on anti-piracy watch was initiated to warn all vessels to maintain a vigilant watch at all times in the SS. The RSN and SPCG were notified of the incident. Information was shared with the Indonesian authority.
6	HK Tug 3/LKH 9889 Tug Singapore 253 9399686	20/04/2026 16:30 LT	MALACCA STRAIT In the precautionary area of the Traffic Separation Scheme (TSS) Malaysia 01° 17.45' N 104° 09.37' E	While the tug boat towing barge was underway, the Chief Officer noticed a sampan and two perpetrators sighted onboard the barge. The perpetrators subsequently left the barge and escaped in the sampan. Some scrap metal were stolen. The crew were not injured. The vessels continued their voyage, with the master declaring that no assistance was required. The incident was reported to Maritime and Port Authority of Singapore (MPA) (flag State). Singapore Port Operations Control Centre (POCC) confirmed that this information has been shared with the Republic of Singapore Navy's (RSN) Maritime Security Task Force (MSTF), Singapore Police Coast Guard (PCG) and Indonesian authority.	Some scrap metal were stolen. The crew were not injured.	Nil	Yes The incident was reported to Singapore MPA (flag State).	ReCAAP-ISC	Singapore POCC confirmed that this information has been shared with RSN's MSTF, Singapore PCG and Indonesian authority.
7	Honour 25 Product tanker Palau 1988 1099735	21/04/2026 11:40 UTC	INDIAN OCEAN Around 6nm SSW of Durdura, Somalia Somalia 08° 56.31' N 050° 32.84' E	While underway, the tanker was boarded and hijacked by 30 persons armed with RPG and AK47s. The incident is ongoing and being monitored by Authorities.	Persons took hostage all crew members and hijacked the tanker	NA	Yes MSCIO & UKMTO	IMBKL	Authorities are monitoring the tanker
8	Taipan Tanker Marshall Islands 86505 9996393	22/04/2026 00:10 LT	MALACCA STRAIT Approximately 3.6 nm west off Pulau Cula, Indonesia, in the eastbound lane of the TSS Indonesia 01° 03.40' N 103° 37.50' E	While underway, a crew member sighted four perpetrators with knives in the engine room. The general alarm was activated and all crew mustered and accounted for. A search was conducted with no further sighting of perpetrators. The crew were not injured and some engine spares were stolen. The incident was reported to Singapore Vessel Traffic Information System (VTIS). Safety broadcast on anti-piracy watch was carried out to warn all vessels to maintain a vigilant watch at all times in the Singapore Strait (SS). The Republic of Singapore Navy's (RSN) Maritime Security Task Force (MSTF) and Singapore Police Coast Guard (SPCG) were notified of the incident. Information was shared with the Indonesian authority.	Some engine spares were stolen. The crew were not injured.	The general alarm was activated and all crew mustered and accounted for. A search was conducted with no further sighting of perpetrators onboard.	Yes The incident was reported to Singapore VTIS.	ReCAAP-ISC	Safety broadcast on anti-piracy watch was initiated to warn all vessels to maintain a vigilant watch at all times in the SS. The RSN's MSTF and SPCG were notified of the incident. Information was shared with the Indonesian authority.

IN PORT AREA									
1	King Milo Bulk carrier Panama 40850 9609512	15/04/2026 LT	MALACCA STRAIT Bahodopi, Indonesia Anchorage. Indonesia 02° 47.20' S 122° 09.39' E	While at anchor, the ship was boarded by the perpetrators. Some brass items such as fire hose coupling, nozzles, cargo light wires, ship's bell and butterfly nuts inside the Bosun Store were stolen. The crew were not injured. The incident was reported to the National Search and Rescue Agency of the coastal States.	Some brass items such as fire hose coupling, nozzles, cargo light wires, ship's bell and butterfly nuts inside the Bosun Store were stolen. The crew were not injured.	Not stated.	Yes The incident was reported to the National Search and Rescue Agency of Indonesia.	ReCAAP-ISC	Not stated.
2	Posh Eagle Tug Singapore 3513 9658252	20/04/2026 20:15 LT	INDIAN OCEAN Outer Anchorage B, near beaching area of Chittagong, Bangladesh 22° 21.34' N 091° 41.86' E	While at anchor, the crew observed unauthorised persons on deck and alerted the bridge. The general alarm was sounded and all crew mustered. Upon detection, the perpetrators fled and jumped into a small boat. A thorough search was conducted. The paint store lock was damaged and 10 cans of paint were stolen. The crew were not injured. The incident was reported to Singapore MPA (flag State).	The paint store lock was damaged and 10 cans of paint were stolen. The crew were not injured.	The general alarm was sounded and all crew mustered. A thorough search was conducted.	Yes The incident was reported to Singapore MPA (flag State).	ReCAAP-ISC	Not stated.
3	CS Saker Product tanker Singapore 30038 1046647	25/04/2026 20:00 UTC	MALACCA STRAIT Sandakan Anchorage, Malaysia Singapore 05° 49.10' N 118° 08.10' E	During routine rounds, duty crew onboard an anchored tanker noticed ship's properties missing. On reporting the theft to local authorities, the coastguard and marine police boarded the tanker for inspection.	Ship's properties were stolen	A search was carried out	Yes Local authorities	IMBKL	Coastguard and marine police boarded the tanker for inspection

* * *

Acts of piracy and armed robbery allegedly attempted against ships reported by Member States or international organizations in consultative status									
N°	Ship Name Type of Ship Flag Gross Tonnage IMO Number	Date Time	Position of the incident*	Details of the incident	Consequences for crew, ship, cargo	Action taken by the master and the crew	Was the incident reported to the coastal authority? Which one?	Reporting State or international organization	Coastal State Action Taken
1	2	3	4	5	6	7	8	9	10
IN INTERNATIONAL WATERS									
1	Elfriede General cargo ship Barbados 6395 9300946	23/04/2026 07:20 UTC	INDIAN OCEAN Around 43nm SE of Garacad, Somalia Somalia 06° 23.80' N 049° 49.10' E	Members of an armed security team onboard a ship underway noticed a skiff approaching rapidly. Alarm raised, speed increased, crew mustered in a safe place and the armed team took their positions. At a distance of around 600m meters there was an exchange of fire between the four pirates on the skiff and the armed team, resulting in the pirates aborting and moving away. All crew members are reported safe and unharmed.	NA	Armed security team onboard	Yes Yes. MSCIO	IMBKL	NA

* The position given should be as accurate as possible including latitude and longitude co-ordinates or as a bearing and distance from a conspicuous landmark
NOTE: SOUTH AMERICA: (A) - Atlantic; (C) - Caribbean; (P) - Pacific

* The position given should be as accurate as possible including latitude and longitude co-ordinates or as a bearing and distance from a conspicuous landmark

NOTE: SOUTH AMERICA: (A) - Atlantic; (C) - Caribbean; (P) - Pacific