

ANNEX									
Acts of piracy and armed robbery allegedly committed against ships reported by Member States or international organizations in consultative status									
N°	Ship Name Type of Ship Flag Gross Tonnage IMO Number	Date Time	Position of the incident*	Details of the incident	Consequences for crew, ship, cargo	Action taken by the master and the crew	Was the incident reported to the coastal authority? Which one?	Reporting State or international organization	Coastal State Action Taken
1	2	3	4	5	6	7	8	9	10
IN TERRITORIAL WATERS									
1	Stellata Product tanker Malta 57997 9732230	03/07/2025 19:35 UTC	MALACCA STRAIT Singapore, Straits Singapore 01° 06.55' N 103° 44.56' E	The duty crew on routine rounds, onboard a tanker underway, spotted six unauthorised persons near the stern. Alarm raised, resulting in the Ship's General alarm sounded. Upon hearing the alarm, the persons escaped without stealing anything. The incident was reported to the Singaporean Authorities. All crew are reported safe.	Nil	Alarm raised and general alarm sounded.	Yes Singapore authorities	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ. (IMBKL)	NA
2	Medi Palmarola Bulk carrier Liberia 43015 9802205	03/07/2025 20:38 UTC	MALACCA STRAIT Singapore Straits Liberia 01° 05.84' N 103° 44.09' E	Duty crew onboard the ship underway observed four individuals disembarking from the stern. The alarm was immediately raised, and all crew members mustered and accounted for. Inspections revealed that spare parts for the generator had been stolen. The incident was reported to Singapore VTIS. Upon reaching Singapore, the police coast guard boarded the ship for an investigation and confirmed the theft of spare parts.	Spare parts for the generator had been stolen.	Alarm raised, crew mustered, and a search was carried out.	Yes Singapore VTIS	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ. (IMBKL)	NA
3	AL Lulu Bulk carrier Marshall Islands 33044 9583627	05/07/2025 16:30 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 02.79' N 103° 39.52' E	Five robbers armed with a pistol boarded a ship underway and entered the engine room. Duty engineer noticed the robbers at the workshop and raised the alarm. Master made a PA announcement and crew mustered. Hearing the alarm, the robbers escaped with stolen ship's engine spares. Incident reported to VTIS. The coast guard boarded the ship at the anchorage for inspection.	Ship's engine spares stolen.	Alarm raised and general alarm sounded.	Yes Singapore VTIS	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ. (IMBKL)	The coast guard boarded the ship at the anchorage for inspection.
4	Kota Nabil Container ship Singapore 20902 9356830	06/07/2025 12:30 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 02.70' N 103° 39.29' E	Duty crew on rounds onboard a ship underway noticed four robbers, on deck, with a long knife and immediately notified the OOW. Alarm raised and crew mustered. Hearing the alarm, the robbers escaped. A search was made and found the steering gear room padlock was broken into. Nothing reported stolen.	Steering gear room padlock was broken.	Alarm raised and general alarm sounded.	No	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ. (IMBKL)	NA

* The position given should be as accurate as possible including latitude and longitude co-ordinates or as a bearing and distance from a conspicuous landmark
NOTE: SOUTH AMERICA: (A) - Atlantic; (C) - Caribbean; (P) - Pacific

5	CMA CGM Fort James Container ship France 73133 9966764	07/07/2025 00:15 LT	MALACCA STRAIT Approximately 2.5 nm off Pulau Cula (Indonesia), in the eastbound lane of the TSS Indonesia 01° 03.79' N 103° 40.97' E	<p>While underway, the A/B was doing his security patrol when he noticed the padlock on aft station starboard side was damaged. A search was conducted, with no perpetrators found onboard. Subsequent review of CCTV footage revealed that six perpetrators had boarded the ship from starboard aft station. They escaped from the ship about 10 min later.</p> <p>The incident was reported to Singapore POCC. Safety broadcasts on anti-piracy watch were initiated to warn all vessels to maintain a vigilant watch at all times in the SS. The RSN's MSTF and Singapore PCG were notified of the incident. Information of the incident was shared with the Indonesian authority. Singapore PCG boarded the ship for investigation, and confirmed that all crew members were accounted for, with no injury reported, and nothing was stolen.</p>	<p>All crew members were accounted for, with no injury reported.</p> <p>Nothing was stolen.</p>	A search was conducted, with no perpetrators found onboard.	Yes The incident was reported to Singapore POCC.	Singapore ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)	Safety broadcasts on anti-piracy watch were initiated to warn all vessels to maintain a vigilant watch at all times in the SS. The RSN's MSTF and Singapore PCG were notified of the incident. Information of the incident was shared with the Indonesian authority. Singapore PCG boarded the ship for investigation, and confirmed that all crew members were accounted for, with no injury reported, and nothing was stolen.
6	Tasco Sakorn Tanker Singapore 3609 9523782	08/07/2025 04:00 LT	MALACCA STRAIT Approximately 1.8 nm off Batu Berhanti Light (Indonesia), in the eastbound lane of the TSS Indonesia 01° 10.96' N 103° 51.24' E	<p>While underway, the 2nd Engineer discovered the aft door behind the galley was ajar. Upon entering the engine room, he found that engine stores and spare parts were missing. The crew did a thorough security search, but no perpetrators were found onboard, and no suspicious crafts sighted in the vicinity. All crew members were accounted for, with no injury reported. Internal investigation suggests that perpetrators may have boarded the ship via the skylight hatch located at the poop deck portside provision hatch, and escaped through the aft door.</p> <p>The incident was reported to Maritime and Port Authority of Singapore (MPA).</p>	<p>All crew members were accounted for, with no injury reported.</p> <p>Some engine stores and spare parts were stolen.</p>	A security search was conducted, with no perpetrators found on board.	Yes The incident was reported to Singapore MPA.	Singapore ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)	Nil
7	Name Withheld Product tanker Denmark 43648	08/07/2025 18:20 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 03.59' N 103° 41.31' E	Six unauthorised persons boarded the tanker underway and entered the engine room. Alarm raised and crew mustered. Seeing the crew alertness, the perpetrators escaped with the stolen engine spares. The incident was reported to VTIS. All crew members reported safe.	Steering gear room padlock, Rope storeroom padlock and Engine Casing door padlock were broken into. Ship's engine spares were stolen.	Alarm raised, crew mustered, and a search was carried out.	Yes VTIS Singapore	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ. (IMBKL)	NA

8	Torm Elizabeth Tanker Denmark 43648 9850006	09/07/2025 02:22 LT	MALACCA STRAIT Approximately 1.8 nm off Pulau Cula (Indonesia), in the eastbound lane of the TSS Indonesia 01° 03.59' N 103° 41.31' E	While underway, the crew spotted a blue wooden boat alongside port quarter of ship. The master raised the alarm and the crew mustered. Upon hearing the alarm, six perpetrators were observed escaping into the boat. A security search was conducted, with no perpetrators found onboard. The padlocks for the deck store, steering gear room and engine casing were found broken. Few items of ship stores were stolen. The crew was not injured. The incident was reported to Singapore POCC. Safety broadcasts on anti-piracy watch were initiated to warn all vessels to maintain a vigilant watch at all times in the SS. The RSN's MSTF was notified of the incident. Information of the incident was shared with the Indonesian authority.	The crew was not injured. Few items of ship stores were stolen.	The master raised the general alarm and mustered the crew. A security search was conducted, with no perpetrators found onboard.	Yes The incident was reported to Singapore POCC.	Singapore ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)	Safety broadcasts on anti-piracy watch were initiated to warn all vessels to maintain a vigilant watch at all times in the SS. The RSN's MSTF was notified of the incident. Information of the incident was shared with the Indonesian authority.
IN PORT AREA									
1	Nordseraphina Container ship Cyprus 18508 1025552	04/07/2025 20:20 UTC	MALACCA STRAIT Belawan Anchorage, Indonesia Indonesia 03° 54.29' N 098° 46.29' E	Four robbers armed with knives boarded an anchored ship. They threatened the duty OS & AB and tied them up. Officer on watch did not receive a response from the duty crew and immediately raised the alarm. Seeing the crew alertness, the robbers escaped with ship's properties, ship's stores, and crew personnel effects. The incident was reported to VTS.	The crew were threatened and tied up. Ship's properties, ship's stores, and crew personnel effects were stolen.	Alarm raised and general alarm sounded.	Yes Belawan VTS	Indonesia PRC relayed the message to Indonesian Marine Police HQ. (IMBKL)	NA
2	Kalolimnos LPG tanker Liberia 13794 9796705	09/07/2025 20:20 UTC	INDIAN OCEAN Chattogram Anchorage, Bangladesh Bangladesh 22° 08.19' N 091° 43.79' E	Seven unauthorised individuals boarded an anchored tanker. Alarm raised resulting in the persons escaping without stealing anything. All crew reported safe.	Nil	Alarm raised.	Yes NA	Bangladesh PRC relayed the message to Bangladesh Coast Guard. (IMBKL)	NA
3	Happy Avocet LPG tanker Denmark 13549 9694373	20/07/2025 07:40 UTC	SOUTH AMERICA (C) Cartagena Anchorage, Colombia Colombia 10° 18.18' N 075° 33.11' W	Duty crew onboard an anchored tanker noticed two robbers armed with knives and immediately notified the bridge. Alarm raised resulting in the perpetrators escaping. A search was conducted and nothing was reported stolen.	NIL	Alarm raised and a search was carried out.	Yes Port Control	Colombia PRC relayed the message to Colombia Authorities. (IMBKL)	NA

* * *

**Acts of piracy and armed robbery allegedly attempted against ships reported by
Member States or international organizations in consultative status**

N°	Ship Name Type of Ship Flag Gross Tonnage IMO Number	Date Time	Position of the incident*	Details of the incident	Consequences for crew, ship, cargo	Action taken by the master and the crew	Was the incident reported to the coastal authority? Which one?	Reporting State or international organization	Coastal State Action Taken
1	2	3	4	5	6	7	8	9	10
IN TERRITORIAL WATERS									
1	Al Salmi Tanker Kuwait 162625 9534793	06/07/2025 14:10 UTC	MALACCA STRAIT Singapore Straits. Singapore 01° 03.29' N 103° 38.20' E	Duty crew onboard the tanker underway, observed three perpetrators in a craft approaching from the stern. Alarm raised and searchlight directed towards the boat resulting in the boat aborting the attempted approach. Incident reported to VTIS and a patrol vessel responded and followed the tanker for a while.	NIL	Alarm raised and searchlight directed towards the boat resulting in the boat aborting the attempted approach.	Yes Singapore VTIS	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ (IMBKL)	A patrol vessel responded and followed the tanker for a while.

* The position given should be as accurate as possible including latitude and longitude co-ordinates or as a bearing and distance from a conspicuous landmark
NOTE: SOUTH AMERICA: (A) - Atlantic; (C) - Caribbean; (P) - Pacific