Resolution A.1023(26) Adopted on 2 December 2009
(Agenda item 10)

CODE FOR THE CONSTRUCTION AND EQUIPMENT OF MOBILE OFFSHORE DRILLING
UNITS, 2009 (2009 MODU CODE)
Corrigendum





ASSEMBLY 26th session Agenda item 10 A 26/Res.1023/Corr.1 17 January 2011 Original: ENGLISH

Resolution A.1023(26)

Adopted on 2 December 2009 (Agenda item 10)

CODE FOR THE CONSTRUCTION AND EQUIPMENT OF MOBILE OFFSHORE DRILLING **UNITS, 2009 (2009 MODU CODE)**

Corrigendum

CHAPTER 3 SUBDIVISION, STABILITY AND FREEBOARD

In paragraph 3.6.5, subparagraph .3, the words "SOLAS regulation II-1/25-9.2" are replaced with the words "SOLAS regulation II-1/13-1".

CHAPTER 13 HELICOPTER FACILITIES

- In paragraph 13.5.15, the reference to "figure 13-5" is replaced with "figure 13-4".
- 3 In paragraph 13.5.26, subparagraph .8 is amended to read as follows:
 - 8." reach full intensity in not more than three seconds at all times;".

Appendix

Model form of Mobile Offshore Drilling Unit Safety Certificate (2009)

4 In the first three lines of the certificate, i.e.:

> "Issued under the provisions of the IMO CODE FOR THE CONSTRUCTION AND EQUIPMENT OF MOBILE OFFSHORE DRILLING UNITS, 2009",

the word "IMO" is deleted.



Resolution A.1023(26) Adopted on 2 December 2009
(Agenda item 10)

CODE FOR THE CONSTRUCTION AND EQUIPMENT OF MOBILE OFFSHORE DRILLING
UNITS, 2009 (2009 MODU CODE)
Corrigendum