

REPORT OF THE MARITIME SAFETY COMMITTEE ON ITS
EIGHTY-NINTH SESSION
Corrigendum

MARITIME SAFETY COMMITTEE
89th session
Agenda item 25

MSC 89/25/Add.1/Corr.1
22 January 2015
Original: ENGLISH

**REPORT OF THE MARITIME SAFETY COMMITTEE ON ITS
EIGHTY-NINTH SESSION**

Corrigendum

ANNEX 12

**RESOLUTION MSC.323(89)
(adopted on 20 May 2011)**

**ADOPTION OF AMENDMENTS TO THE REVISED RECOMMENDATION ON TESTING
OF LIFE-SAVING APPLIANCES (RESOLUTION MSC.81(70))**

Existing paragraph 14 of the annex is replaced with the following:

"14 The text of the existing paragraph 6.2.2 is modified to read as follows:

"When inherent buoyant material is required, the material should be subjected to the tests prescribed in 2.6, other than 2.6.8, except that in 2.6.6.3 high-octane petroleum spirit should be substituted for diesel oil."

REPORT OF THE MARITIME SAFETY COMMITTEE ON ITS
EIGHTY-NINTH SESSION
Corrigendum