

<p style="text-align: center;"><b>ANNEX</b>  <b>Acts of piracy and armed robbery allegedly committed against ships reported by</b>  <b>Member States or international organizations in consultative status</b></p>									
N°	Ship Name Type of Ship Flag Gross Tonnage IMO Number	Date Time	Position of the incident*	Details of the incident	Consequences for crew, ship, cargo	Action taken by the master and the crew	Was the incident reported to the coastal authority? Which one?	Reporting State or international organization	Coastal State Action Taken
1	2	3	4	5	6	7	8	9	10
<b>IN INTERNATIONAL WATERS</b>									
1	JSP Vento General cargo ship Portugal 7138 9570656	01/02/2025 21:35 UTC	WEST AFRICA Around 40nm WNW of Bata, Equatorial Guinea Equatorial Guinea 02° 02.00' N 009° 07.00' E	Three armed pirates boarded the ship underway. Alert crew raised the alarm, sent a distress alert via VHF radio and all crew retreated into the citadel. Once the pirates left the ship the crew emerged from the citadel and sailed to a safe port. The crew noticed on radar a target which appeared to be following the ship. After a while the target disappeared. All crew reported safe. Authorities are investigating the incident.	All crew retreated into the citadel	Alert crew raised the alarm, sent a distress alert via VHF radio and all crew retreated into the citadel	Yes NA	PRC received the incident report from the Authorities. (IMBKL)	NA
<b>IN TERRITORIAL WATERS</b>									
1	Haima Oil product tanker Panama 59705 9397896	01/02/2025 06:00 LT	MALACCA STRAIT 1.4 nm west of Helen Mar Reef (Indonesia), in the eastbound lane of the TSS Indonesia 01° 07.80' N 103° 45.00' E	While underway, an engine department crew member sighted five perpetrators coming out of the engine room. The engineer immediately reported to the chief engineer, who then informed the bridge. The alarm was raised and a search was conducted with no perpetrators found. A surveillance camera recording in the engine room also revealed the perpetrators coming out of the engine room. The crew was not injured. Nothing was stolen.  The incident was reported to the Maritime and Port Authority of Singapore (MPA). The shipping company also reported the incident to the Maritime Bureau of the Ministry of Land, Infrastructure, Transport and Tourism (MLIT) of Japan.	The crew was not injured.  Nothing was stolen	The alarm was raised and a search was conducted with no perpetrators found.	Yes The incident was reported to MPA.	Japan ReCAAP ISC via ReCAAP Focal Point (Japan) (ReCAAP)	No information available
2	Belaja Bulk carrier Norway 35048 9873280	02/02/2025 19:50 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 02.78' N 103° 39.34' E	Four robbers armed with gun and knives boarded the ship underway. 3/E was taken hostage and tied up in the engine room. The 3/E managed to escape and informed the Master. Alarm raised, ship's horn sounded, and crew mustered. Seeing the alerted crew, the robbers escaped with stolen engine spares. The incident was reported to VTIS West.	3/E was taken hostage and tied up in the engine room. Ship's engine spares were stolen.	Alarm raised, ship's horn sounded, and crew mustered.	Yes VTIS West	Indonesia PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ. (IMBKL)	NA
3	Zevirous Product tanker Malaysia 1934 9132856	02/02/2025 20:15 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 06.00' N 103° 45.00' E	Six robbers armed with knives boarded the tanker underway. They entered the engine room, took the 2/E and 3/E hostage, and tied them up. The robbers stole engine spares prior to escaping. Alarm raised and crew mustered. The incident was reported to VTIS West and Central.	2/E and 3/E were taken hostage and tied up. Ship's engine spares were stolen.	Alarm raised and crew mustered.	Yes VTIS West and Central	Indonesia PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ. (IMBKL)	NA

\* The position given should be as accurate as possible including latitude and longitude co-ordinates or as a bearing and distance from a conspicuous landmark.  
NOTE: SOUTH AMERICA: (A) - Atlantic; (C) - Caribbean; (P) - Pacific

4	Al Najma No.481 Dhow Yemen	07/02/2025	EAST AFRICA Around 6NM SE of Eyl, Somalia Somalia 07° 54.00' N 049° 56.00' E	Six persons boarded and hijacked the dhow and took its crew including a Somali guard, hostage. The guard was later released. Authorities are investigating the incident.  Reports indicate the perpetrators left the dhow on or before 13 February 2025, after stealing crew personal effects. All crew safe.	Crew personal effects were stolen.	NA	Yes NA	Somalia PRC received incident report from the Authorities. (IMBKL)	Eunavfor Atalanta assets spotted the dhow that was abandoned by the hijackers.
5	Cancun Bulk carrier Liberia 107129 9587269	14/02/2025 02:55 LT	MALACCA STRAIT 2.5 nm northwest of Pulau Cula (Indonesia), in the eastbound lane of the TSS Indonesia 01° 04.34' N 103° 41.11' E	While underway, four perpetrators, of whom one carried gun and three carried knives, were sighted in the engine room. The alarm was raised and all crew mustered to conduct a search with no further sighting of perpetrators. The crew was not injured and nothing was stolen.  The incident was reported to Singapore VTIS. Safety navigational broadcast was initiated. The RSN's MSTF and Singapore PCG were notified of the incident. Singapore PCG boarded the ship, conducted a search, and no perpetrator was found. Information of the incident was shared with the Indonesian authorities.	The crew was not injured.  Nothing was stolen.	The alarm was raised and crew mustered to conduct a search with no further sighting of perpetrators.	Yes The incident was reported to Singapore VTIS.	Singapore ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)	Safety broadcast was initiated. The RSN's MSTF and Singapore PCG were notified of the incident. Singapore PCG boarded the ship, conducted a search and no perpetrator was found. Information of the incident was shared with the Indonesian authorities.
6	Atrotos Heracles Bulk carrier Panama 43007 9668879	15/02/2025 20:45 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 05.50' N 103° 43.79' E	Duty crew onboard a bulk carrier underway noticed three unauthorized individuals at the aft stations. Alarm raised and crew mustered. Seeing the crew alertness, the individuals escaped empty handed. The incident reported to VTIS. Upon anchoring, the vessel was boarded by the coast guard for investigations.	Nil	Alarm raised and crew mustered.	Yes Singapore VTIS	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ.	Coast guard boarded the vessel for investigations.
7	Pelicana General cargo ship Norway 39258 9401790	16/02/2025 02:00 LT	MALACCA STRAIT Approx. 2 nm northwest of Pulau Cula (Indonesia), in the eastbound lane of the TSS Indonesia 01° 03.72' N 103° 41.22' E	While underway, four perpetrators armed with long knives were sighted boarding from the portside quarter and heading to the engine room. The master raised the alarm and all crew mustered to conduct a search. The crew was not injured. Some electrical and engine room items were stolen.	The crew was not injured.  Some electrical and engine room items were stolen.	The crew was not injured.  Some electrical and engine room items were stolen.	No	Singapore ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)	Not known

8	Atrotos Heracles Bulk carrier Panama 43007 9668879	16/02/2025 04:45 LT	MALACCA STRAIT 3.5 nm northeast of Pulau Cula (Indonesia), in the eastbound lane of the TSS Indonesia 01° 05.76' N 103° 43.93' E	While underway, three perpetrators were sighted at the aft station. Upon raising the emergency alarm, the three perpetrators escaped from the ship. A security search was conducted onboard. The crew was not injured. Nothing was stolen.  The incident was reported to Singapore VTIS. Safety broadcast on anti-piracy watch was initiated to warn all vessels to maintain a vigilant watch at all times in SS. The RSN's MSTF and Singapore PCG were notified of the incident. Singapore PCG boarded the ship upon her arrival at Singapore bunkering anchorage. A search was conducted and no perpetrator was found. Information of the incident was shared with the Indonesian authorities.	The crew was not injured.  Nothing was stolen.	The alarm was raised and crew mustered to conduct a search onboard.	Yes The incident was reported to Singapore VTIS.	Singapore ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)	Safety broadcast on anti-piracy watch was initiated to warn all vessels to maintain a vigilant watch at all times in SS. The RSN's MSTF and Singapore PCG were notified of the incident. Singapore PCG boarded the ship upon her arrival at the Singapore bunkering anchorage. A search was conducted and no perpetrator was found. Information of the incident was shared with the Indonesian authorities.
9	Saytuun 2 Fishing vessel Yemen	17/02/2025 00:01 UTC	EAST AFRICA Off Garmaal, North of Eyl, Somalia Somalia	Six armed pirates hijacked the fishing vessel and took the Captain and four crew members as hostage. The remaining crew were released. Reports suggest the vessel may be used as a mothership for maritime criminal activities. On 23 February 2025, a Spanish naval vessel identified the fishing vessel and boarded it. The crew indicated that the pirates had left the vessel. All crew safe.	The fishing vessel was hijacked. The Captain and four crew members were taken as hostages.	NA	Yes Puntland Police, Somalia	PRC received the incident report from the Authorities. (IMBKL)	On 23.02.2025, a Spanish naval vessel boarded the fishing vessel after identifying it. The crew confirmed that the pirates had already left, and all crew members were found to be safe.
10	Cycladic Spire Bulk carrier Portugal 20254 9609330	22/02/2025 03:10 LT	MALACCA STRAIT Approx. 3.5 nm west of Pulau Cula (Indonesia), in the eastbound lane of the TSS Indonesia 01° 02.75' N	While underway, three perpetrators armed with knives and gun-like object were sighted in the engine room. The emergency alarm was raised and crew mustered. A security search was conducted and no perpetrators were found. The crew was not injured. Some engine spares were stolen.  The incident was reported to Singapore Vessel Traffic Information System (VTIS). Safety broadcast on anti-piracy watch was initiated to warn all vessels to maintain a vigilant watch at all times in the Singapore Strait (SS). The Republic of Singapore Navy's (RSN) Maritime Security Task Force (MSTF) and Singapore Police Coast Guard (PCG) were notified of the incident. Singapore PCG boarded the ship upon her arrival in Singapore. A search was conducted and no perpetrator was found. Information of the incident was shared with the Indonesian authorities.	The crew was not injured.  Some engine spares were stolen.	The emergency alarm was raised and crew mustered to conduct a security search onboard.	Yes The incident was reported to Singapore VTIS.	Singapore ReCAAP ISC via ReCAAP Focal Point (Singapore) (ReCAAP)	Safety broadcast on anti-piracy watch was initiated to warn all vessels to maintain a vigilant watch at all times in the SS. The RSN's MSTF and Singapore PCG were notified of the incident. Singapore PCG boarded the ship upon Darrival in Singapore. A search was conducted and no perpetrator was found. Information of the incident was shared with the Indonesian authorities.
11	Ocean Diligence Bulk carrier Marshall Islands 35716 9967134	25/02/2025 21:20 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 05.96' N 103° 44.15' E	Duty crew onboard the ship underway noticed a skiff in the vicinity of the ship. Three unauthorised persons were noticed onboard and attempting to open the accommodation doors. Alarm raised, resulting in the persons escaping without stealing anything. VTIS Central informed. Upon anchoring the coast guard boarded the ship for inspection.	NIL	An emergency alarm was raised, and the crew used flashlights to deter the persons from opening the accommodation doors and ISPS grill door.	Yes VTIS Central	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ.	The coast guard boarded the ship at AEBB anchorage for inspection.

12	Ifestos Bulk carrier Bahamas 50617 9574133	27/02/2025 16:30 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 06.19' N 103° 43.90' E	Duty crew onboard a bulk carrier underway spotted six robbers armed with a hammer in the engine room workshop. Alarm raised, crew mustered and a search was conducted. Incident reported to Singapore Coast Guard who then escorted the vessel. All crew safe and nothing reported stolen.	Nil	Alarm raised, crew mustered and a search was conducted.	Yes Singapore Coast Guard	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ. (IMBKL)	A patrol vessel escorted the ship.
13	DSM Rose General cargo ship Barbados 21385 9303601	27/02/2025 17:10 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 05.59' N 103° 43.50' E	Five robbers in a fishing boat boarded a ship underway and entered the engine room. They threatened the 2/E with a gun, instructing him to move away. The 2/E retreated and raised the alarm. Crew mustered and a search was conducted. Ship's property was reported stolen. The incident was reported to local authorities.	2/E was threatened with a gun. Ship's property was reported stolen.	Alarm raised, crew mustered and a search was conducted.	Yes Singapore VTIS	Singapore PRC relayed the message to Singapore Police Coast Guard & Indonesian Marine Police HQ.	NA
14	Manali Bulk carrier Panama 19829 9268916	28/02/2025 17:00 UTC	MALACCA STRAIT Singapore Straits Singapore 01° 04.19' N 103° 41.70' E	Four robbers armed with a gun and knives boarded a ship underway. They entered the engine room, threatened one crew, stole engine spares and escaped. The crew informed the Master. General alarm raised, PA announcement made and SSAS activated. Incident reported to VTIS. Upon anchoring, the vessel was boarded by the coast guard for investigations.	One crew was threatened and engine's spares were stolen.	Alarm raised, PA announcement made and SSAS activated.	Yes Singapore VTIS & Singapore Police Coast Guard	Singapore PRC relayed the message to Singapore Police Coast Guard. (IMBKL)	A patrol boat was dispatched and boarded for investigation.
<b>IN PORT AREA</b>									
1	Eurotrader Product tanker Malta 29723 9895927	24/02/2025 23:38 UTC	WEST AFRICA Takoradi Anchorage, Ghana Ghana 04° 53.00' N 001° 42.00' W	Duty crew onboard an anchored tanker spotted two unauthorised persons. Alarm raised and port control notified resulting in the persons escaping without stealing anything.	Nil	Alarm raised and port control notified.	Yes Port Control	Ghana PRC received the incident report from the Authorities.	NA